

ADDENDUM NO. 2
To the Plans and Specifications for:

**IMPLEMENTATION OF BMPs WITHIN THE SUNSET BEACH
WATERSHED (PHASE VI) (674) (SCHEDULES A-G)**

City of Treasure Island

1. **BID DATE: NO CHANGE**
Monday, December 18, 2017 @ 2:00 p.m.
2. **TECHNICAL SPECIFICATIONS: NO CHANGES**
3. **PLANS: NO CHANGES**
4. **RESPONSE TO QUESTIONS:**

RSQ.1 Page 4 of 6 from Addendum 1 , states

GC.9 Compensation for unsuitable material removal and replacement will only be provided when unsuitable material is located beneath the bedding of a pipe and/or structure. Unsuitable material that resides above this elevation shall be removed, and disposed of, at the Contractor's expense.

Below the Pipe Bedding , Unsuitable material will be paid to Contractor under the appropriate Bid Items

while

Above the Pipe Bedding Unsuitable material will **not** be covered by those same Bid Items.

Question : Are you saying that the material above the pipe is Suitable to be placed back in the Trench ? _____

Contractor requests a copy of any New Soil Borings/Geotechnical reports, if applicable , that may be used to determine the above requirement form GC.9.

The Contractor's above statement is correct regarding the compensation limits for unsuitable material removal and replacement. However, please note GC.9 also identifies structures.

The geotechnical report, included within the specifications, identified two (2) soil strata that were observed at the locations of the borings. These strata were identified as suitable backfill material per Page 4 of the report.

No new geotechnical information was obtained. This City-standard clause was found to be excluded at the time of addendum preparation. As such, it was included in Addendum No. 1.

5. GENERAL INFORMATION/ CLARIFICATIONS: N/A

CITY OF TREASURE ISLAND

December 13, 2017